

# Bruce Baker Enterprises, Inc.

Restoration and Porsche® Specialist  
7 Crosskeys Road  
Collegeville, PA 19426  
610-831-1200 Fax: 610-831-1205  
E-mail: [bbspdstr@aol.com](mailto:bbspdstr@aol.com)  
[www.356restoration.com](http://www.356restoration.com) or [www.bbakerent.com](http://www.bbakerent.com)

February 5, 2014

Robert Boyle  
4 Willow Avenue  
North Hampton, NH 03862  
603-397-3700 (Office)  
603-379-2265 (Home)  
973-214-3626 (Cell)

Subject: 1959 Porsche 356A Cabriolet, VIN 151896

Date	Labor	Hours	Labor Cost	Parts	Parts Cost	Credit	Total
<i>Labor last billed through July 30, 2013</i>							
8/8/13	Last minute bodywork	3.5	\$ 280.00				
8/17/13	Tape and prep for poly primer, spray	1.5	120.00				
8/23/13	Work on 'nose' area, weld unneeded holes	2.0	160.00				
8/28/13	Continued bodywork, sanding on front end	3.75	300.00				
8/30/13	Sand contours of front end	4.0	320.00				
9/3/13	Re-work lower nose contour, reshape to better average, sand doors and front fenders	4.75	380.00				
9/4/13	Bodywork, smooth front valance, fit bumper parts, tape/mask, re-coat with fill primer	8.0	640.00				

Date	Labor	Hours	Labor Cost	Parts	Parts Cost	Credit	Total
9/5/13	Smooth rear valance, rear bumper fit with brackets, add primer, sand gaps, edges, sides (2 techs)	10.0	800.00				
9/6/13	Re-contour rear left corner to match right side, re-fit bumper, prep for re-primer	8.0	640.00				
9/7/13	Details of rear half, sand, primer	3.75	300.00				
9/9/13	Front details, door low spot, rear low spot, re-prime as needed	4.0	320.00				
9/12/13	Assemble bumper for trial fit	2.5	200.00				
9/13/13	Prep bumper ends, block, sand body	2.0	160.00				
9/16/13	Continued bumper fit, measure, make and fill holes, fit guards, supports, brackets, decos, etc.	8.0	640.00				
9/17/13	Add poly filler as needed on front bumper, drill new deco holes in rear bumper, sand and smooth	8.0	640.00				
9/18/13	Sand jambs and perimeters, whole shell	4.0	320.00				
9/20/13	Jamb details, fill and sand, under hood details, primer	3.0	240.00				
9/23/13	Smooth dash, doors, windshield frame, spray polyester, primer as needed, straighten aluminum hinge covers (2 techs)	7.5	600.00				
9/25/13	Finish inside of left door, straighten jamb parts and prime hinge covers	1.5	120.00				
9/26/13	Finish body sanding, smoothing	1.5	120.00				

Date	Labor	Hours	Labor Cost	Parts	Parts Cost	Credit	Total
9/27/13	Assemble reconditioned headlight parts	1.0	80.00				
9/28/13	Continued sanding of body	1.0	80.00				
10/22/13	Fit headlights with seals, sand primer, fill and sand primer on fenders, re-spray primer as needed	4.5	360.00				
10/24/13	Guide-coat, sanding, spot primer, sand with boards, touch up primer (2 techs all day)	10.0	800.00				
10/25/13	Final sanding, prep and mask for final primer, 'cut-in' red as appropriate (2 techs all day)	10.0	800.00				
10/28/13	Un-tape, clean, remove doors, inner and under details	3.0	240.00				
10/29/13	Spray inner doors with primer	3.5	280.00				
10/31/13	Fine-sand and prime jambs and lids, undersides	4.0	320.00				
11/1/13	Prep, mask and urethane primer, cut-in black on ends, edges, cavities (2 techs)	10.0	800.00				
11/2/13	Wet-sand dash, seal and paint	3.0	240.00				
11/4/13	Bake, color-sand and polish	1.5	120.00				
11/6/13	Mask dash, wet-sand body	2.75	220.00				
11/8/13	Continued wet-sanding, prep small parts and pieces, sand and paint inner door tops with ruby red (2 techs)	8.0	640.00				
11/14/13	Wet-sand shell, correct minor details, do paint prep, clean	4.0	320.00				
11/15/13	Clean and mask for paint, touch up undercoat	3.75	300.00				
11/19/13	Paint shell black	3.5	280.00				
11/20/13	Wet-sand smoother, add coats of urethane	4.75	380.00				
11/22/13	Paint parts, wet-sand rear shell	5.0	400.00				

Date	Labor	Hours	Labor Cost	Parts	Parts Cost	Credit	Total
11/25/13	Paint bumper and doors, prep and spray	7.0	560.00				
12/5/13	Sand and polish paint	6.5	520.00				
12/6/13	Buff shell and panels (2 techs)	8.0	640.00				
12/9/13	Hang doors after polishing	4.0	320.00				
12/10/13	Continued polishing	1.5	120.00				
12/11/13	Begin assembly, sort parts	1.0	80.00				
12/12/13	Remove pits and nicks on wheels, file edges, straighten bends	4.25	340.00				
12/13/13	Prep wheels and spray with epoxy primer	2.0	160.00				
12/19/13	Sand and prep wheels for silver paint, miscellaneous assembly on car (3 techs)	6.5	520.00				
12/20/13	Add 5 hubcap clips on wheels	.5	40.00				
12/23/13	Paint trunk, install trunk seal, add insulation in doors, wet-sand paint on hood	4.0	320.00				
12/24/13	Sand and polish parts of car to make better, place panels on body	3.25	260.00				
12/26/13	Sand and buff / polish rear bumper, brush-paint black urethane in engine compartment	4.0	320.00				
12/27/13	Strip gas tank, minor dent removal, sand, spray with epoxy primer	4.0	320.00				
12/30/13	Install steering box, wiring, hood, sound deadening	3.25	260.00				
12/31/13	Prep and sand gas tank	.5	40.00				
1/2/14	Add fuel, brake lines and throttle rod, install trans, add more tar paper insulation, begin brake assembly (3 techs)	6.0	480.00				

Date	Labor	Hours	Labor Cost	Parts	Parts Cost	Credit	Total
1/4/14	Blast insides of brake drums, strip outsides and scrub with WD-40, paint gas tank with urethane primer	3.0	240.00				
1/6/14	Sand and seal gas tank, install brake backing plates, shim, rebuild cylinders (hone and check), continued application of sound deadener (3 techs)	6.5	520.00				
1/7/14	Paint insulation front and rear, find better rear drum, blast and clean, steel-wool (4), begin brake cylinder installation	2.5	200.00				
1/8/14	Brake assembly, arc shoes to fit, blast and acid-etch rusty hardware, clad sheaths on park brake cables	2.0	160.00				
1/9/14	Re-hab original parts, continued brake work and insulation installation (3 techs)	6.5	520.00				
1/10/14	Assembly, add tunnel parts, hand brake, door window chrome, miscellaneous pieces, latches and catches, clean out heater cable tubes, blast and prime small parts (2 techs)	3.5	280.00				
1/11/14	Paint tank straps, fix door window lifts	2.5	200.00				
1/13/14	Underside blackening, wiring, add front grilles and horn mounts	2.5	200.00				
1/14/14	Install new front bearings, polish rear grille, dual reservoir, plumbing, threshold mats and trim, door checks, miscellaneous trim (3 techs all day)	9.0	720.00				

Date	Labor	Hours	Labor Cost	Parts	Parts Cost	Credit	Total
1/15/14	Fit front latch, add ID plaques, chase threads, glue gas tank pads, miscellaneous assembly	4.5	360.00				
1/16/14	Assemble doors, handles, chrome, clean gaskets, re-hab glove box and door pad, wiring, finish sills, fresh air vents, pad gas tank straps, fit mats, etc. (3 techs)	10.0	800.00				
1/17/14	Vent window assembly, polish trim and aluminum, clean shifter parts, fittings, wipers, battery box cover, inner assembly of latches and hardware (2 techs)	4.0	320.00				
1/18/14	Polish trim (and file), continued assembly	3.5	280.00				
1/20/14	Chrome assembly, re-fit horn brackets, miscellaneous assembly, horns, etc.	2.5	200.00				
1/23/14	Begin bumper assembly, lights, tach cable, clean and paint small parts	2.0	160.00				
1/24/14	Assemble re-chromed original front turn signals, relay re-hab, add starter	2.0	160.00				
1/27/14	Wiring, grounds, rear lights, reflectors, miscellaneous assembly	2.0	160.00				
1/28/14	Begin rear bumper assembly, wiring of lights and dash	3.25	260.00				
1/29/14	Rivet vent window pivots, swap door glass in support channels, install cables in tunnel, grounding strap on trans to body pedal linkages, parking brake cables	4.5	360.00				

Date	Labor	Hours	Labor Cost	Parts	Parts Cost	Credit	Total
1/30/14	Test wiper motor, wiper parts, side door mirror, add dash parts, bumper assembly, paint front bumper (3 techs)	7.75	620.00				
1/31/14	Install gas tank, sender, fast idle, fuel lines, Speedo cable, wiring of dash, assemble windshield (3 techs)	9.0	720.00				
	<i>Total labor</i>	333.75					\$26,700.00
				(2) lap belts @\$39.15/ea	\$ 78.30		
				Gas tank level sending unit	116.10		
				Interior light NLA-632-101-03	42.00		
				(4) 'baby moon' hubcaps @\$68.00/ea	272.00		
				(2) special bolts for rear over-riders @\$14.25/ea	28.50		
				(2) special cap nuts for rear over-riders @\$1.03./ea	2.06		
				(2) black seals for top-to-door glass @\$42.50/ea	85.00		
				Aluminum channels on top frame, set	16.46		
				Radio block off plate	25.00		
				Reutter badge	15.00		
				(2) 'A' rocker deco inserts @\$13.60/ea	27.20		
				(2) 'A' rocker deco base gaskets @\$29.65/ea	59.30		
				New brake light switch	29.35		
				Dual master cylinder	47.50		
				(2) 'U' channels for threshold @\$9.15/ea	18.30		
				(2) rubber seals for threshold @\$11.75/ea	23.50		

Date	Labor	Hours	Labor Cost	Parts	Parts Cost	Credit	Total
				(2) inner front wheel bearings @\$35.33/ea	70.66		
				(2) outer front wheel bearings @\$26.23/ea	52.46		
				(2) oil seals for front @\$4.70/ea	9.40		
				(2) better repro horn grilles @\$22.00	44.00		
				(2) better repro horn grille gaskets @\$12.90/ea	25.80		
				(4) Boge shocks @\$58.45/ea	233.80		
				(4) qts, all-metal filler @\$32.00/ea	128.00		
				Spies-Hecker spray polyester primer (at cost)	314.88		
				Silver base paint for wheels (at cost), reducer (at cost w/tax)	305.58		
				Matting agent (at cost)	60.53		
				Activator (at cost)	35.40		
				Spies-Hecker permasolid black	189.17		
				Polyester putty, tube (at cost)	23.43		
				Mequire's polishes (at cost)	59.78		
				Windshield gasket from Veloce Space (at cost)	198.22		
				Shipping for above	25.00		
				Windshield, Sigla	647.50		
				(2) windshield trim @\$55.50/ea (at cost)	111.00		
				(2) windshield trim connectors @\$4.25/ea	8.50		
				(2) ball pin for rear top turnbuckles @\$9.90/ea	19.80		



Date	Labor	Hours	Labor Cost	Parts	Parts Cost	Credit	Total
				(2) original headlight lenses, new @\$135.90/ea	271.80		
				15 Amp voltage drop (at cost w/ shipping)	85.00		
				(2) good used rear light inner reinforcements @\$5.00/ea	10.00		
				(5) Vredestein 165 x 15 tires @\$125.00/ea w/shipping	625.00		
				Differential for better rear lights	100.00		
				Better front bumper (at cost w/shipping)	326.53		
				Zim's 12v geared lightweight starter w/shipping	244.54		
				(2) door handle set screws for tumbler @\$.70/ea	1.40		
				Headlight-to-body seals @\$5.25/ea	10.50		
				(2) rubber door stops @\$21.55/ea	43.10		
				Door handle casting, chrome, source: Porsche	244.80		
				(2) vent bolts @\$59.90/ea	119.80		
				Handle hardware	22.85		
				Tunnel brake line	20.00		
				(2) front brake hoses @\$20.00/ea	40.00		
				(2) rear brake hoses @\$22.00/ea	44.00		
				Rear right brake line	25.00		
				Rear left brake line	25.00		
				Front left brake line	20.00		
				Front right brake line	22.00		
				Dual reservoir (VW)	20.00		

Date	Labor	Hours	Labor Cost	Parts	Parts Cost	Credit	Total
				(8) brake cylinder rebuild kits @\$8.00/ea	64.00		
				(4) luggage strap loops @\$10.00/ea	40.00		
				(2) large door handle gaskets @\$4.00/ea	8.00		
				(2) small door handle gaskets @\$4.00/ea	8.00		
				(4) black rear lid buffers @\$2.50/ea	10.00		
				(2) door bump stops @\$4.50/ea	9.00		
				Hand brake cable boot	5.00		
				Threshold trim set w/mats and hardware	145.00		
				(4) tie-rod ends @\$25.00/ea	100.00		
				(2) short cab top turnbuckles @\$15.10/ea	30.20		
				(2) trim adhesive / tubes @\$6.50/ea	13.00		
				(11) liquid nails / tubes @\$29.50/ea	32.45		
				Qt, contact cement	15.50		
				(3) aerosol glue @\$15.50/ea	46.50		
				Miscellaneous metric hardware, 114 pieces @\$0.50/ea	57.00		
				Shop supplies	49.00		
				Sound deadening mat (Eastwood)	39.00		
				(2) rubber boots @\$6.05/ea	12.10		
				(2) receiver sets (lock-handle) @\$98.00/ea	196.00		
				Porsche handle crest	36.00		

Date	Labor	Hours	Labor Cost	Parts	Parts Cost	Credit	Total
				Hood handle, excellent repro	219.09		
				Screw set NLA-541-005-00	3.05		
				(4) screw and spacer @\$10.15/ea	40.60		
				Shifter ball	12.75		
				Rods for heater, pair, new	9.50		
				(2) gray straps for cable hanging at rear @\$15.90/ea	31.82		
				New inside mirror	98.16		
				(2) profile NLA-559-591-00 @\$4.52/ea	9.04		
				Hose, vent	2.75		
				(2) profile, 644-505-391-00 @\$3.75/ea	7.50		
				Cover, 644-21-270-00	77.29		
				(2) clamps @\$9.78/ea	19.56		
				(2) door glass @\$81.26/ea	162.52		
				(2) profile, 644-531-951-00 @\$3.50/ea	7.00		
				(2) grommets @\$3.05/ea	6.10		
				(2) grommets @\$4.35/ea	8.70		
				(2) air intake seals @\$21.75/ea	5.50		
				(4) door seals (under panel) @\$8.65/ea	17.30		
				Boot, 356-23-204	6.05		
				(2) heater hoses @\$5.10/ea	10.20		
				(2) headlight seals @\$5.25/ea	10.50		
				(2) 4mm x 6mm aluminum rivets @\$0.21/ea	.42		
				Foot pump diaphragm	9.95		
				Fuel valve	114.70		

Date	Labor	Hours	Labor Cost	Parts	Parts Cost	Credit	Total
				Rubber pad (for jack holder)	1.00		
				(2) heat control cables @ \$22.94/ea	45.88		
				Gasket, NLA-559-003-00	10.95		
				Glove box door liner	78.20		
				Fuel rod aluminum plate	36.65		
				Windshield rod hole plug	1.35		
				Hood seal, 644-511-091-06	27.50		
				Screw set for above	9.04		
				(2) original re-chromed front bayonet lens units, rebuilt, complete @ \$150/ea	300.00		
				Door inner latch pull rod	17.10		
				(5) wheel hubcap clips for rivets @ \$1.85/ea	9.25		
				(117) pieces of metric hardware, miscellaneous @ \$.50/ea	58.50		
				New speedometer cable	38.95		
				New tachometer cable core	27.05		
				Rear lid grille hardware set	2.55		
				Rear lid grille gasket	4.52		
				(6) heat control rod clamps, used @ \$4.00/ea	24.00		
				(2) sun visors (set)	249.00		
				(2) "fuzzy" channels for door windows @ \$20.00/ea	40.00		
				Good used battery cover and spring clamps	50.00		
				(2) door check rubber wedges @ \$21.55/ea	43.10		
				Paint prep supplies (at cost)	137.33		

Date	Labor	Hours	Labor Cost	Parts	Parts Cost	Credit	Total
				Black paint (urethane) (at cost)	487.90		
				(6) qts, Spies-Hecker 3508 primer (at cost)	302.58		
				Polishing materials (at cost)	<u>72.72</u>		
				<i>Total parts</i>			9,650.72
	<i>Sub-contract:</i>						
	Mount and balance 5 wheels and tires		\$ 75.00				
	Skim-cut 4 brake drums		<u>100.00</u>				
	<i>Total sub-contract</i>						175.00
	<i>Shipping:</i>						
	Bumper, out		\$46.94				
	<i>Total Shipping</i>						<u>46.94</u>
	<i>Sub-total</i>						\$36,572.66
	Remainder, bill of 8/3/13						<u>540.70</u>
	<i>Sub-total</i>						\$37,113.36
	Total credits - Paypal 8/9/13						<u>-8,000.00</u>
	<b>TOTAL DUE</b>						<b>\$29,113.36</b>