

5105 Willowmeade Dr. Fairfax, VA 22030 703-266-1356 Tel 866-808-3402 Fax

Invoice

Date	Invoice #
10/23/2012	437

Customer:

Robert Boyle
P.O. Box 668
North Hampton, NH 03862

Qty	Description		Rate	Total
	Estimate for rebuild of 1959 Porsche transaxle serial #27036 Rebuild labor on 644/716/741 Transaxle, to include cleaning, disassembly, reassemble and ring and pinion setup. All components inspected. Parts magnafluxed as required. Case blasted with walnut shells to remove corrosion. All internal parts ultrasonically cleaned.			1,150.00
	Blast and paint axle tubes, include labor to press tubes in and out of bearing housings and install solid boots if required.		275.00	275.00
	Setup gaskets and clearance for axle tubes		175.00	175.00
	Grind main shaft for larger differential housing clearance		95.00	95.00T
	Modify case for late clutch release bearing guide tube		95.00	95.00T
1	. - '		1,250.00	1,250.00T
1			550.00	550.00T
1	1 12 bolt differential housing cover		300.00	300.00T
2	2 Axle Boot Solid		18.20	36.40T
1	1 Gasket Set, Transaxle		57.00	57.00T
1	Bearing, Rear Pinion ShaftPOR only 716/741		238.00	238.00T
1			80.25	80.25T
1	1 Bearing I plate Pinion shaft tunnel case 900.053.003.00		90.25	90.25T
1	1 Bearing, Rear Mainshaft 716/741		98.42	98.42T
1	Bearing, Diff Housing		33.75	33.75T
1	Bearing, diff housing cover		47.92	47.92T
2	Rear wheel bearing		24.00	48.00T
2	Seal Kit, Drum Brake		23.27	46.54T
12	Late 19mm ATF ring gear bolt		18.00	216.00T
1	Differential Pinion Lock Pin		2.58	2.58T
1	Clutch fork kit, 741 with new roll pins and case bushings		85.00	85.00T
1	Clutch cross shaft return spring		15.00	15.00T
1	Late clutch release bearing guide tube		75.00	75.00T
	Subtot	Subtotal		
	Sales -	Sales Tax (0.0%)		

Total

Payments/Credits

Balance Due



5105 Willowmeade Dr. Fairfax, VA 22030 703-266-1356 Tel 866-808-3402 Fax

Invoice

Date	Invoice #	
10/23/2012	437	

Customer:

Robert Boyle
P.O. Box 668
North Hampton, NH 03862

Qty	Description		Rate	Total
1	644/716 shift selector		189.40	189.40T
	Pin, Bearing Housing		1.02	2.04T
1	Starter bushing		7.65	7.65T
2	Axle, 356		125.00	250.00T
2	Fulcrum plate		20.00	40.00T
	Plated hardware 716 transaxle		40.00	40.00T
1	.40 pinion shim		9.00	9.00T
1	.30 pinion shim		11.00	11.00T
	Differential spacer Std bearing pin 3.0 Std		12.00 1.53	24.00T 85.68T
	Differential gear set		1.33	175.00T
1	Bell crank shaft		173.00	173.001 12.00T
1	Clutch bowden tube bracket		45.00	45.00T
2	Wheel seal spacer		38.25	76.50T
~	Shop supplies		45.00	45.00T
		Subtotal	\$6,072.38	
		Sales Tax (0.0	9%) \$0.00	
		Total		\$6,072.38
		Payments/Cre	dits	6-5,634.20
		Balance D	ue	\$438.18